


ORIGINAL



SDMS DocID

2241160

manifests:

Generator copies



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

2500-FM-LRWM0051 REV. 7/99

P.O. Box 8550  
Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

ORIGINAL

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020  
4. Generator's Phone (215) 814-3272

2531  
12th St.

A. State Manifest Document Number

PAG 183505

B. State Gen. ID

SAME

5. Transporter 1 Company Name

Elk Transportation, Inc.

6. US EPA ID Number

PAD987271020

C. State Trans. ID

PA-AH

PA AH0413

7. Transporter 2 Company Name

8. US EPA ID Number

D. Transporter's Phone (610) 372-4760

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15690

10. US EPA ID Number

PAD004835146

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Hazardous waste, solid, n.o.s. (Contains  
Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

X / X

DT XXX 23

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

a) ERG# 171

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emergency Svc.: 800-851-7156

SITE: 12TH STREET LANAPIC  
YUKON, PENN. DE

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE

Signature

Michael Towle

MONTH

DAY

YEAR

04

11

01

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Raymond J. SUREK

Signature

Raymond J. Surek

MONTH

DAY

YEAR

04

11

01

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

ORIGINAL

Form approved.  
OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information within the bold red border is not required by Federal law but may be required by State law.	
3. Generator's Name and Mailing Address U.S. Environmental Protection Agency 1650 Arch Street Philadelphia, PA 19103-2020		HS31 12th St	DEP00000167783504	A. State Manifest Document Number <b>PAG 183504</b>		
4. Generator's Phone (215) 814-3272		5. Transporter 1 Company Name Elk Transportation, Inc.	6. US EPA ID Number PAD987271020	B. State Gen. ID <b>SAME</b>		
7. Transporter 2 Company Name		8. US EPA ID Number	C. State Trans. ID <b>PA-AH PA AH0413</b>			
9. Designated Facility Name and Site Address Mill Services, Inc. RD#1, Box 135A Yukon, PA 15698		10. US EPA ID Number PAD004835146	D. Transporter's Phone (610) 372-4760			
			E. State Trans. ID <b>PA-AH</b>			
			F. Transporter's Phone ( )			
			G. State Facility's ID			
			H. Facility's Phone (724) 722-3500			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) HM		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. <input checked="" type="checkbox"/> RQ, Hazardous waste, solid, n.o.s. (Contains Lead), 9, NA3077, PGIII D008		XXI	DT	XX23	T	D008
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above S		K. Handling Codes for Wastes Listed Above				
		a. c.				
		b. d.				
15. Special Handling Instructions and Additional Information a) ERG# 171 BILL TO: Elk Transportation, Inc., 225 Warren St., Reading, PA 19601 24 Hr Emgcy Svc.: 800-851-7156 SITE: 12TH STREET LANDFILL BIRMINGHAM, DC						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name MICHAEL TOWLE, EPA-OSC		Signature <i>Michael Towle</i>		MONTH DAY YEAR 04 11 01		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name James E. Hollenbach SR		Signature <i>James E. Hollenbach</i>		MONTH DAY YEAR 04 11 01		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		MONTH DAY YEAR		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19. Printed/Typed Name Signature MONTH DAY YEAR						

PAG 183504

6

## INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

### GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

### GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

### TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

### DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

HS31  
12TH ST. site

4. Generator's Phone ( )

215 814-3272

5. Transporter 1 Company Name

Elk Transportation, Inc.

6. US EPA ID Number

PAD987271020

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004835146

A. State Manifest Document Number

PAG 183503

B. State Gen. ID

SAME

C. State Trans. ID

PA-AH

PA AH0413

D. Transporter's Phone ( )

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( )

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

a. X RQ, Hazardous waste, solid, n.o.s. (Contains  
Lead), 9, NA3077, FRIII D008

XXI

DT

XX23

I

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

a) ERG#: 171

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

SITE: 12TH STREET LANDFILL  
MILFINGTON, DE

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE

Signature

Michael Towle

MONTH DAY YEAR

04 11 01

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

WAYNE C MOHR

Signature

Wayne C Mohr

MONTH DAY YEAR

04 11 01

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

2500-FM-LRW0051 REV. 7/99

P.O. Box 8550  
Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.  
OMB No. 2050-0039

ORIGINAL

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle - HS31

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004035146

A. State Manifest Document Number

PAG 183378

B. State Gen. ID

12th St. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (800) 651-8192

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No. Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01 DT

X22

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-05C

Signature

*Michael Towle*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

TOM SKELTON

Signature

*Tom Skelton*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

ORIGINAL

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020  
4. Generator's Phone (215) 914-3272

A. State Manifest Document Number

PAG 183379

B. State Gen. ID

18th ST. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD 987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD 004835146

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X25

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emergency Svc.: 800-851-7156

DE HW-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL Towle, EPA-OSC

Signature

*Michael Towle*

MONTH

DAY

YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

JERRY Williams

Signature

*Jerry Williams*

MONTH

DAY

YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

ORIGINAL

Form approved.  
OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD 987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Tukon, PA 15698

10. US EPA ID Number

PAD 004035146

A. State Manifest Document Number

PAG 183380

B. State Gen. ID

12th St Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone

(888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emergency Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

MONTH DAY YEAR

MICHAEL Towle - EPA OSC

[Signature]

11/20/00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

LUTHER WATT

[Signature]

11/22/00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

ORIGINAL

Form approved.  
OMB No. 2050-0039

2500-FM-LRWMM0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone ( 215 ) 614-3272

5. Transporter 1 Company Name

US BULK TRANSPORT, Inc.

6. US EPA ID Number

PAD98-7347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004835146

A. State Manifest Document Number

PAG 183381

B. State Gen. ID

Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone

888-651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13.  
Total  
Quantity

14.  
Unit  
Wt/Vol

I.  
Waste No.

01

DT

X 22

T

D008

J. Additional Descriptions for Materials Listed Above

5

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Michael Towle, EPA OSC

Signature

Michael Towle

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

GREGORY A. LINTZ

Signature

Gregory A. Lintz

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

ORIGINAL

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020  
4. Generator's Phone ( 215 ) 814-3272

TOWLE-HS31

5. Transporter 1 Company Name

US BULK TRANSPORT, Inc.

6. US EPA ID Number

PAD 987.347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD 004835146

A. State Manifest Document Number

PAG 183382

B. State Gen. ID

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone ( 588 ) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)  
HM

a. X RQ. Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGLII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X 25

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emergency Svc.: 800-851-7156

DE-HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

ERIK PAUL KELLY

Signature

*Erik Paul Kelly*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of      - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

ORIGINAL

Form approved.

OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle - HS31

5. Transporter 1 Company Name

6. US EPA ID Number

US Bulk Transport, Inc.

PAD987 347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

10. US EPA ID Number

Mill Services, Inc.  
RD#1, Box 135A  
Tukon, PA 15690

PAD004835146

A. State Manifest Document Number

PAG 183383

B. State Gen. ID

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X25

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-351-7156

DE HW405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

Michael Towle

MONTH

DAY

YEAR

12

20

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Kevin TAPPER

Signature

Kevin Tapper

MONTH

DAY

YEAR

12

20

00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

ORIGINAL

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD 98 7347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD 004835146

A. State Manifest Document Number

PAG 183384

B. State Gen. ID

Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

D T

X 24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgoy Svc.: 800-851-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWNE, EPA-OSC

Signature

*Michael Towne*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

EDWARD C. HENR

Signature

*Edward C. Henry*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

ORIGINAL

Form approved.  
OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 1		Information within the bold red border is not required by Federal law but may be required by State law.		
3. Generator's Name and Mailing Address U.S. Environmental Protection Agency 1650 Arch Street Philadelphia, PA 19103-2020						A. State Manifest Document Number <b>PAG 183385</b>				
4. Generator's Phone ( 215 ) 814-3272						B. State Gen. ID <b>DEMSI, LANDFILL W. MINGTON, DE</b>				
5. Transporter 1 Company Name <b>US Bulk Transport</b>						C. State Trans. ID <b>PA-AH 0408</b>				
6. US EPA ID Number <b>PAD 987347515</b>						D. Transporter's Phone <b>(888) 651-8152</b>				
7. Transporter 2 Company Name						E. State Trans. ID <b>PA-AH</b>				
8. US EPA ID Number						F. Transporter's Phone ( )				
9. Designated Facility Name and Site Address Mill Services, Inc. RD#1, Box 135A Yukon, PA 15698						G. State Facility's ID				
10. US EPA ID Number <b>PAD 004835146</b>						H. Facility's Phone ( 724 ) 722-3500				
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>HM</b>						12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. <b>X</b> <b>RQ, Waste Hazardous waste, solid, n.o.s. (Contains Lead), 9, NA3077, PGIII D008</b>						No.	Type			
b.						<b>01</b>	<b>DT</b>	<b>X 24</b>	<b>T</b>	<b>D008</b>
c.										
d.										
J. Additional Descriptions for Materials Listed Above <b>S</b>						K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information <b>BILL TO: Elk Transportation, Inc., 225 Warren St., Reading, PA 19601</b>						24 Hr Emgcy Svc.: 800-851-7156				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.										
Printed/Typed Name <b>MICHAEL TOWLE</b>						Signature <i>Michael Towle</i>		MONTH <b>12</b>	DAY <b>20</b>	YEAR <b>00</b>
17. Transporter 1 Acknowledgement of Receipt of Materials										
Printed/Typed Name <b>JAMES TENARY</b>						Signature <i>James Tenary</i>		MONTH <b>12</b>	DAY <b>20</b>	YEAR <b>00</b>
18. Transporter 2 Acknowledgement of Receipt of Materials										
Printed/Typed Name						Signature		MONTH	DAY	YEAR
19. Discrepancy Indication Space										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.										
Printed/Typed Name						Signature		MONTH	DAY	YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.

OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transportation

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

A. State Manifest Document Number

PAG 183386

B. State Gen. ID

13th St. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone

(888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X 23

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE-HW-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

Michael Towle

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Dennis Capola

Signature

Dennis Capola

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

DM = Metal drums, barrels, kegs, pails	DT = Dump truck
DW = Wooden drums, barrels, kegs, pails	CY = Cylinders
DF = Fiberboard or plastic drums, barrels, kegs, pails	CM = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
TP = Tanks portable	CW = Wooden boxes, cartons, cases, pallets
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases, pallets
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

G = Gallons (liquid only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

Form approved.

OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 2

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport Inc.

6. US EPA ID Number

PA D 987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA D 004835146

A. State Manifest Document Number

PAG 183387

B. State Gen. ID

12th St. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone

688, 658182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

122

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-651-7156

DE-HW-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOUL, EPA OSC

Signature

[Signature]

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Todd STAPPENBECK

Signature

[Signature]

MONTH DAY YEAR

11 22 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.  
OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport

6. US EPA ID Number

PAD 987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD 004835146

A. State Manifest Document Number

PAG 183388

B. State Gen. ID

W/12/15/14/15/11  
Wilmington DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone

(610) 658882

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, D.O.S.  
(Contains Lead), 9, NA3077, PGIII 0008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X23

T

0008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emergency Svc.: 800-251-7156

DE-HW-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE EPA OSC

Signature

Michael Towle

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

DAVID L. LATHROP

Signature

David L. Lathrop

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

TOWLE-H531

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD987 347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Tukon, PA 15698

10. US EPA ID Number

PAD004835146

A. State Manifest Document Number

PAG 183389

B. State Gen. ID 12th St Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

No.

Type

Quantity

Unit  
Wt/Vol

I. Waste No.

01

DT

X 24

I

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE 76W-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSL

Signature

Michael Towle

MONTH

DAY

YEAR

12

20

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

MARI PROCKER

Signature

Mari Procker

MONTH

DAY

YEAR

12

20

00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. Do not use decimals or fractions.
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

TOUPE-11531

5. Transporter 1 Company Name

6. US EPA ID Number

US Bulk Transport, Inc.

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

10. US EPA ID Number

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

PA0004035146

A. State Manifest Document Number

PAG 183390

B. State Gen. ID

18th S. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII 2008

No.

Type

01

D T

X25

T

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

S

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

MONTH DAY YEAR

MICHAEL TOUPE EPA-OSC

[Signature]

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

Steve Collier

[Signature]

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

TOWLE H531

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15650

10. US EPA ID Number

PA0004835146

A. State Manifest Document Number

PAG 183391

B. State Gen. ID 1st SP. Landfill  
Wilmington DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (858) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X25

T

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emergency Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Deanna Munshower

Signature

*Deanna Munshower*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US BULK TRANSPORT, Inc.

6. US EPA ID Number

PAD987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004835146

A. State Manifest Document Number

PAG 183392

B. State Gen. ID 12th St Landfill

Wilmington DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (858) 651-8152

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII 0008

12. Containers

No. Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

D T

X25

T

0008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Randy Akin

Signature

*Randy Akin*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020  
4. Generator's Phone (215) 814-3272

A. State Manifest Document Number

PAG 183393

B. State Gen. ID

2451-11  
Wilmington, DE

5. Transporter 1 Company Name

US Bulk Transport, Inc

6. US EPA ID Number

PA0987347515

C. State Trans. ID

PA-AH 040F

7. Transporter 2 Company Name

8. US EPA ID Number

D. Transporter's Phone

(888) 651-5142

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RDFI, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9. NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Hal Anderson

Signature

*Hal Anderson*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

## INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

### GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

### GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

### TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

### DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport, Inc.

7. Transporter 2 Company Name

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15690

10. US EPA ID Number

EAD004835146

A. State Manifest Document Number

PAG 183394

B. State Gen. ID 12th St Landfill  
Wilmington DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

01

D T

X25

T

D008

J. Additional Descriptions for Materials Listed Above

3

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Mik Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr. Emergency Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

*Michael Towle*

MONTH

DAY

YEAR

12

20

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

TOMMY HENRY

Signature

*Tommy Henry*

MONTH

DAY

YEAR

12

20

00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020  
4. Generator's Phone ( 215 ) 814-3272

A. State Manifest Document Number

PAG 183395

B. State Gen. ID 124 ST. LANDFILL  
Wilmington, DE

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0987347515

C. State Trans. ID

PA-AH 0408

7. Transporter 2 Company Name

8. US EPA ID Number

D. Transporter's Phone (888) 651-8152

E. State Trans. ID

PA-AH

9. Designated Facility Name and Site Address

Will Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE JW405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL Towle, EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12 20 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

JEFFREY LEONARD

Signature

*Jeffrey Leonard*

MONTH DAY YEAR

12 20 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT. (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

TOWLE H531

5. Transporter 1 Company Name

6. US EPA ID Number

US Bulk Transport, Inc.

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

10. US EPA ID Number

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

PA0004835146

A. State Manifest Document Number

PAG 183396

B. State Gen. ID 12th ST LANDFILL

Wilmington, DE

C. State Trans. ID

PA-AH 0408 531/3A

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)  
HM

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NAC077, PGIII D008

No.

Type

01

DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-051-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

MONTH DAY YEAR

MICHAEL TOWLE, EPA OSC

[Signature]

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

LUTHER WATT

[Signature]

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone ( 215 ) 814-3272

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD 987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD 004835146

A. State Manifest Document Number

PAG 183397

B. State Gen. ID

12th St Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone ( 888 ) 657-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGLII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X 24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW-405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-DC

Signature

Michael Towle

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

EDWARD L. ITOMP

Signature

Edward L. Itomp

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA; but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



## PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

## OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWMM0051 REV. 7/99

Form approved.

OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.2. Page 1  
of 1Information within the bold red border is  
not required by Federal law but may be  
required by State law.

## 3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

TOWLE HS31

## 5. Transporter 1 Company Name

6. US EPA ID Number

US Bulk Transport, Inc. | PAD987347515

## 7. Transporter 2 Company Name

8. US EPA ID Number

## 9. Designated Facility Name and Site Address

10. US EPA ID Number

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

PAD004835146

## A. State Manifest Document Number

PAG 183398

B. State Gen. ID 12th St Landfill  
Wilmington DE

## C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

## E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

## G. State Facility's ID

H. Facility's Phone (724) 722-3500

## 11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

## 12. Containers

13. Total  
Quantity14. Unit  
Wt/Vol

1. Waste No.

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

01 DT

X24

D008

b.

c.

d.

## J. Additional Descriptions for Materials Listed Above

S

## K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

## 15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

## 16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

## Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

## Signature

Michael Towle

MONTH DAY YEAR

12/21/00

## 17. Transporter 1 Acknowledgement of Receipt of Materials

## Printed/Typed Name

KEVIN TAPPER

## Signature

Kevin Tapper

MONTH DAY YEAR

12/21/00

## 18. Transporter 2 Acknowledgement of Receipt of Materials

## Printed/Typed Name

## Signature

MONTH DAY YEAR

## 19. Discrepancy Indication Space

## 20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

## Printed/Typed Name

## Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

DM = Metal drums, barrels, kegs, pails	DT = Dump truck
DW = Wooden drums, barrels, kegs, pails	CY = Cylinders
DF = Fiberboard or plastic drums, barrels, kegs, pails	CM = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
TP = Tanks portable	CW = Wooden boxes, cartons, cases, pallets
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases, pallets
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

G = Gallons (liquid only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone ( 215 ) 814-3272

Towle HS 31

5. Transporter 1 Company Name

6. US EPA ID Number

US Bulk Transport, Inc.

PAD987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

10. US EPA ID Number

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

PAD004835146

A. State Manifest Document Number

PAG 183399

B. State Gen. ID 12th St Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (885) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

a. X HM RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

01

D T

X24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 900-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Michael Towle, EPA-05C

Signature

Michael Towle

MONTH

12

DAY

21

YEAR

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Brian Bousie

Signature

Brian Bousie

MONTH

12

DAY

21

YEAR

00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).

PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 614-3272

Towle HSB

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004835146

A. State Manifest Document Number

PAG 183400

B. State Gen. ID

12th St & Arch

Wilmington DE

C. State Trans. ID

PA-AH

0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

HM  
a. X HQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

No.

Type

Est.

20

T

D008

b.

c.

d.

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

MICHAEL TOWLE EPA-OSC

Michael Towle

12

28

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone ( 215 ) 814-3272

TOWLE HS 31

5. Transporter 1 Company Name

US BULK TRANSPORT, Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004935146

A. State Manifest Document Number

PAG 183401

B. State Gen. ID

1212 ST. LANDFILL  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone ( 888 ) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No. Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

EST  
24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Bulk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA OSC

Signature

Michael Towle

MONTH DAY YEAR

12 22 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

EDWARD C. HENP

Signature

Edward C. Henp

MONTH DAY YEAR

12 22 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

DM = Metal drums, barrels, kegs, pails	DT = Dump truck
DW = Wooden drums, barrels, kegs, pails	CY = Cylinders
DF = Fiberboard or plastic drums, barrels, kegs, pails	CM = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
TP = Tanks portable	CW = Wooden boxes, cartons, cases, pallets
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases, pallets
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

G = Gallons (liquid only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RDF#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004035146

A. State Manifest Document Number

PAG 183402

B. State Gen. ID

12th St. LANDRII

C. State Trans. ID

PA-AH 0908

D. Transporter's Phone (888) 651-9142

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12/21/00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

TOM SKELTON

Signature

*Tom Skelton*

MONTH DAY YEAR

12/21/00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

DM = Metal drums, barrels, kegs, pails	DT = Dump truck
DW = Wooden drums, barrels, kegs, pails	CY = Cylinders
DF = Fiberboard or plastic drums, barrels, kegs, pails	CM = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
TP = Tanks portable	CW = Wooden boxes, cartons, cases, pallets
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases, pallets
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

G = Gallons (liquid only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020  
4. Generator's Phone ( 215 ) 814-3272

TOWLE H531

A. State Manifest Document Number

PAG 183403

B. State Gen. ID 12th ST Landfill  
Wilmington, DE

5. Transporter 1 Company Name

6. US EPA ID Number

US Bulk Transport, Inc.

1 PAD 987347515

C. State Trans. ID

PA-AH 0408

7. Transporter 2 Company Name

8. US EPA ID Number

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

9. Designated Facility Name and Site Address

10. US EPA ID Number

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

PA D 0 0 4 8 3 5 1 4 6

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

I. Waste No.

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

No.

Type

01

D T

X25

T

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

Michael Towle

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

JAMES TENARY

Signature

James Tenary

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle HS31

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA09E7347515

7. Transporter 2 Company Name

8. US EPA ID Number

A. State Manifest Document Number

PAG 183404

B. State Gen. ID 12th St Landfill

Wilmington, DE

C. State Trans. ID PA-AH 0408

D. Transporter's Phone 888 1651-5182

E. State Trans. ID PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA00C4835146

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII 0008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X23

T

0008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE EPA-OSC

Signature

Michael Towle

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Todd Stappenbeck

Signature

Todd Stappenbeck

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

## INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

### GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

### GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

### TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

### DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.

OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PAD 987 347 515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD 004 635 146

A. State Manifest Document Number

PAG 183405

B. State Gen. ID

12th St Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (855) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

61

DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR  
12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Dennis Capel

Signature

*Dennis Capel*

MONTH DAY YEAR  
12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of      - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



## PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION

Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

## OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.

OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.2. Page 1  
ofInformation within the bold red border is  
not required by Federal law but may be  
required by State law.

## 3. Generator's Name and Mailing Address

## A. State Manifest Document Number

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

PAG 183406

4. Generator's Phone ( 215 ) 814-3272

TOWLE 11531

B. State Gen. ID 12th ST. Landfill  
Wilmington, DE

## 5. Transporter, 1 Company Name

AS Bulk Transport, Inc.

## 6. US EPA ID Number

IPAD987347515

## C. State Trans. ID

PA-AH 6408

## 7. Transporter 2 Company Name

## 8. US EPA ID Number

D. Transporter's Phone ( 888 ) 651-8182

## E. State Trans. ID

PA-AH

## F. Transporter's Phone ( )

## G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

## 9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

## 10. US EPA ID Number

IPAD004835146

## 11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

## 12. Containers

13. Total  
Quantity14. Unit  
Wt/Vol

## 15. Waste No.

a. HM  
X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9. NA3077, PGIII D008

## No.

## Type

Total  
QuantityUnit  
Wt/Vol

## Waste No.

01

D T

X24

T

D008

## J. Additional Descriptions for Materials Listed Above

S

## K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

## 15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgoy Svc.: 800-651-7156

## 16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

## Printed/Typed Name

## Signature

MONTH DAY YEAR

MICHAEL TOWLE, EPA-OSC

Michael Towle

12 21 00

## 17. Transporter 1 Acknowledgement of Receipt of Materials

## Printed/Typed Name

## Signature

MONTH DAY YEAR

ERIK PAUL KELLY

Erik Paul Kelly

12 21 00

## 18. Transporter 2 Acknowledgement of Receipt of Materials

## Printed/Typed Name

## Signature

MONTH DAY YEAR

## 19. Discrepancy Indication Space

## 20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

## Printed/Typed Name

## Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550

Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle H331

5. Transporter 1 Company Name

US BULK TRANSPORT, Inc.

6. US EPA ID Number

1PAD987317515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004835146

A. State Manifest Document Number

PAG 183407

B. State Gen. ID 12th ST. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0405

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-052

Signature

Michael Towle

MONTH

12

DAY

22

YEAR

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

DON BIXLEY

Signature

Don Bixley

MONTH

12

DAY

22

YEAR

00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

DM = Metal drums, barrels, kegs, pails	DT = Dump truck
DW = Wooden drums, barrels, kegs, pails	CY = Cylinders
DF = Fiberboard or plastic drums, barrels, kegs, pails	CM = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
TP = Tanks portable	CW = Wooden boxes, cartons, cases, pallets
TT = Cargo tanks (tank trucks)	CF = Fiber or plastic boxes, cartons, cases, pallets
TC = Tank cars	BA = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

G = Gallons (liquid only)	L = Liters (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs)	M = Metric tons (1000 kg)
Y = Cubic yards	N = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.

OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle HS31

5. Transporter 1 Company Name

US BULK TRANSPORT Inc.

6. US EPA ID Number

IPAD987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PAD004035146

A. State Manifest Document Number

PAG 183408

B. State Gen. ID 12th St. Landfill  
Wilmington DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (858) 651-8162

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ. Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No.

Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01

DT

X23

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE EPA-OSC

Signature

Michael Towle

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Gregory A. Lintz

Signature

Gregory A. Lintz

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

## INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

### GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

### GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CV</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

### TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

### DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.

OMB No. 2050-0039

2500-FM-LRWM0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle 71531

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

A. State Manifest Document Number

PAG 183409

B. State Gen. ID 12th ST. Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8152

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

a. HM RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

No.

Type

Est.

T

D008

X

01

DT

23

T

b.

c.

d.

J. Additional Descriptions for Materials Listed Above

5

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

Truck No. 186

DE HW405

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA - OSC

Signature

Michael Towle

MONTH DAY YEAR

12 22 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

JAMES TENARY

Signature

James Tenary

MONTH DAY YEAR

12 22 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management

P.O. Box 8550

Harrisburg, PA 17105-8550

OFFICIAL PENNSYLVANIA MANIFEST FORM

Form approved.

OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle 21531

5. Transporter 1 Company Name

US Bulk Transport Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Eaton, PA 15698

10. US EPA ID Number

PA D 0 0 4 8 3 5 1 4 6

A. State Manifest Document Number

PAG 183410

B. State Gen. ID (2th St. Landfill)

Wilmington DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

No.

Type

01

DT

X23

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-651-7156

DE H01A05

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

Michael Towle

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

JEFF BALINT

Signature

Jeff Balint

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR



# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRW0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle X531

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0907347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

A. State Manifest Document Number

PAG 183411

B. State Gen. ID 12th St Landfill  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (888) 651-8182

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

No.

Type

01

DT

X22

T

D008

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

DE HW 405

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE EPA-OSC

Signature

Michael Towle

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Gene Lyon

Signature

Gene Lyon

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 6.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description [Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)] - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550  
OFFICIAL PENNSYLVANIA MANIFEST FORM

2500-FM-LRWM0051 REV. 7/99

Form approved.  
OMB No. 2050-0039

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone (215) 814-3272

Towle 21531

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

A. State Manifest Document Number

PAG 183412

B. State Gen. ID 12451 LAMF:11

Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone (833) 1651-5152

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone (724) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM  
a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII D008

12. Containers

No. Type

13. Total  
Quantity

14. Unit  
Wt/Vol

1. Waste No.

01 DT

X24

T

D008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE EPA-OSC

Signature

*Michael Towle*

MONTH DAY YEAR

12 21 00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Dennis Jacklett

Signature

*Dennis Jacklett*

MONTH DAY YEAR

12 21 00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH DAY YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

Signature

MONTH DAY YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.

## GENERAL INFORMATION

For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially. If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

Table I - Types of Containers

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

Table II - Units of Measure

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).



PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Bureau of Land Recycling and Waste Management  
P.O. Box 8550  
Harrisburg, PA 17105-8550

Form approved.  
OMB No. 2050-0039

2500-FM-LRW0051 REV. 7/99

OFFICIAL PENNSYLVANIA MANIFEST FORM

UNIFORM HAZARDOUS  
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest  
Document No.

2. Page 1  
of 1

Information within the bold red border is  
not required by Federal law but may be  
required by State law.

3. Generator's Name and Mailing Address

U.S. Environmental Protection Agency  
1650 Arch Street  
Philadelphia, PA 19103-2020

4. Generator's Phone ( 215 ) 814-3272

Towle - 34531

5. Transporter 1 Company Name

US Bulk Transport, Inc.

6. US EPA ID Number

PA0987347515

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Mill Services, Inc.  
RD#1, Box 135A  
Yukon, PA 15698

10. US EPA ID Number

PA0004835146

A. State Manifest Document Number

PAG 183413

B. State Gen. ID (21K ST - LANDFILL  
Wilmington, DE

C. State Trans. ID

PA-AH 0408

D. Transporter's Phone ( 855 ) 651 8192

E. State Trans. ID

PA-AH

F. Transporter's Phone ( )

G. State Facility's ID

H. Facility's Phone ( 724 ) 722-3500

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

HM

a. X RQ, Waste Hazardous waste, solid, n.o.s.  
(Contains Lead), 9, NA3077, PGIII 0008

12. Containers

No.

Type

13. Total  
Quantity,

14. Unit  
Wt/Vol

I. Waste No.

01

DT

X 23

T

0008

J. Additional Descriptions for Materials Listed Above

S

K. Handling Codes for Wastes Listed Above

a.

c.

b.

d.

15. Special Handling Instructions and Additional Information

BILL TO: Elk Transportation, Inc.,  
225 Warren St., Reading, PA 19601

24 Hr Emgcy Svc.: 800-851-7156

16. GENERATOR'S CERTIFICATION:

I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

MICHAEL TOWLE, EPA-OSC

Signature

Michael Towle

MONTH

DAY

YEAR

12

21

00

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Jersey Williams

Signature

Jersey Williams

MONTH

DAY

YEAR

12

21

00

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

MONTH

DAY

YEAR

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

MONTH

DAY

YEAR

# INSTRUCTIONS FOR COMPLETION OF THE PENNSYLVANIA HAZARDOUS WASTE MANIFEST

**No reproduction of this official Pennsylvania manifest form may be used as a shipping document for shipment of hazardous waste. All copies of this manifest must be legible.**

## GENERAL INFORMATION

**For all shipments of hazardous waste. The copies of the manifest shall be distributed as indicated at the bottom of each copy.**

If there are more than four different waste streams in a shipment, except for lab packs, complete another Manifest. If there are more than two transporters or if the waste is a lab pack, use the Uniform Hazardous Waste Manifest Continuation Sheet. Continuation Sheets must be purchased commercially.

If you have any questions concerning the completion of this Manifest, call 717-783-9258.

## GENERATOR/SHIPPER

- Item 1.** Generator/Shipper's US EPA ID No. - Enter the twelve digit US EPA Identification Number. Manifest Document No. - Assign a five digit number unique to all others assigned by this Generator/Shipper.
- Item 2.** Page 1 of \_\_\_ - Enter the total number of pages used to complete this Manifest counting this Manifest and Continuation Sheets, if any.
- Item 3.** Generator/Shipper's Name and Mailing Address - Enter the complete name of the generator/shipper and the complete mailing address. The address should be the location that will manage the returned Manifest forms.
- Item A.** State Manifest Document Number - This number is pre-printed, do not alter it. This Number must be placed in Item L of each continuation sheet.
- Item B.** State Gen ID - Not required for PA Generators.
- Item 4.** Generator's Phone Number - Enter the area code and telephone number where an authorized agent of the Generator may be contacted.
- Item 5.** Transporter 1 Company Name - Enter the complete company name of the first Transporter who will transport the waste.
- Item 6.** Use EPA ID Number - Enter the twelve digit US EPA Identification Number of the Transporter identified in Item 5.
- Item C.** State Trans. ID - Enter the four digits of the License No. issued by PA DEP.
- Item D.** Transporter's Phone - Enter the area code and the telephone number where an authorized agent of the Transporter may be contacted.
- Item 7.** Transporter 2 Company Name - If applicable, see item 5.
- Item 8.** US EPA ID Number - If applicable, see Item 6.
- Item E.** State Trans. ID - If applicable, see Item C.
- Item F.** Transporter's Phone - If applicable, see Item D.
- Item 9.** Designated Facility Name and Site Address - Enter the complete company name and complete site address of the facility designated to receive the waste listed on this Manifest. The address must be the site address, which may differ from the mailing address.
- Item 10.** US EPA ID Number - Enter the twelve digit US EPA Identification Number of the Designated Facility.
- Item G.** Enter the Facility's State ID Number - Not Required for PA facilities.
- Item H.** Facility's Phone - Enter the area code and phone number where an authorized agent of the Designated Facility may be contacted.
- Item 11.** Enter an X in the HM box if the waste is a hazardous material regulated by U. S. DOT (See 49CFR 172.201 (a) (1)).  
US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number)) - Enter the US DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA Number) for each waste as identified in 49 CFR 171 through 177. For wastes not regulated as hazardous materials by DOT, enter a description of the waste.
- Item 12.** Containers (No. and Type) - Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.
- Item 13.** Total Quantity - Enter the total quantity of each waste. **Do not use decimals or fractions.**
- Item 14.** Unit (Wt/Vol) - Enter the appropriate abbreviation from Table II (below) for the unit of measure.

**Table I - Types of Containers**

<b>DM</b> = Metal drums, barrels, kegs, pails	<b>DT</b> = Dump truck
<b>DW</b> = Wooden drums, barrels, kegs, pails	<b>CY</b> = Cylinders
<b>DF</b> = Fiberboard or plastic drums, barrels, kegs, pails	<b>CM</b> = Metal boxes, cartons, cases (roll-offs, hoppers, gondolas, etc.)
<b>TP</b> = Tanks portable	<b>CW</b> = Wooden boxes, cartons, cases, pallets
<b>TT</b> = Cargo tanks (tank trucks)	<b>CF</b> = Fiber or plastic boxes, cartons, cases, pallets
<b>TC</b> = Tank cars	<b>BA</b> = Burlap, cloth, paper or plastic bags

**Table II - Units of Measure**

<b>G</b> = Gallons (liquid only)	<b>L</b> = Liters (liquids only)
<b>P</b> = Pounds	<b>K</b> = Kilograms
<b>T</b> = Tons (2000 lbs)	<b>M</b> = Metric tons (1000 kg)
<b>Y</b> = Cubic yards	<b>N</b> = Cubic Meters

- Item I.** Waste No. - Enter the Hazardous Waste Number of each waste. Refer to U.S.E.P.A regulations. If a waste is not regulated as hazardous in PA, but is regulated by the Generator State, enter that State's waste code. Also, enter in item J or Item 15, "This waste is not a Hazardous Waste according to PA law."
- Item J.** Additional Descriptions for Materials Listed Above.
- Item K.** Handling Codes for Wastes Listed Above - Not required for PA Generators.
- Item 15.** Special Handling Instructions and Additional Information - Use this space to indicate special transportation, treatment, storage, or disposal information or Bill of Lading information. For international shipments, enter the point of departure (City and State). If the waste will be recycled at the designated facility on this manifest, enter a statement to that effect.
- Item 16.** Generator/Shipper's Certification - Read and sign by hand the certification statement. Enter the date (MM/DD/YY) the waste was shipped. If a mode other than highway was used, the word "highway" should be lined out and the appropriate mode (rail, water, or air) inserted in the space below. If another mode in addition to the highway mode is used, enter the appropriate mode (e.g., and rail) in the space below the certification statement. Primary exporters shipping hazardous waste to a facility located outside the United States must add to the end of the first sentence of the certification the following words "and conforms to the terms of the EPA Acknowledgement of Consent to the shipment."

## TRANSPORTER

- Item 17.** Transporter 1 Acknowledgement of Receipt of Materials - Print or type the name of the person accepting the waste on behalf of the transporter. Sign and enter the date of receipt (MM/DD/YY).
- Item 18.** Transporter 2 Acknowledgement of Receipt of Materials - If applicable, see Item 17.

## DESIGNATED FACILITY

- Item 19.** Discrepancy Indication Space - The Designated Facility's authorized representative must note in this space any significant discrepancy between the waste types or quantities described on the Manifest and those actually received. If waste is rejected, so indicate in this space.
- Item 20.** Facility Owner or Operator: Certification of receipt or rejection of hazardous materials covered by this manifest. Print or type the name of the person accepting or rejecting the waste on behalf of the owner or operator of the facility. Sign and enter the date of the receipt or rejection (MM/DD/YY).